

Cara Mencegah Pengaratan

Ways to Control Rusting

Secara am, terdapat 3 cara untuk mencegah pengaratan, iaitu

1. Menggunakan lapisan perlindungan
2. Pengaloian
3. Perlindungan logam korban

Generally, there are 3 ways to control rusting, which include:

1. **Using protective coating**
2. **Alloying**
3. **Sacrificial protection (sacrificial metal)**

